

RECALL NOTICE

C.A.M.P. USA Inc. ANNOUNCES RECALL OF TOUR NANOTECH AUTOMATIC & SEMI-AUTO CRAMPONS.



RISK: We have discovered inconsistencies in the crimp at the end of the attachment points on the rear heel bail where the bail connects to the crampon. With strong outward pressure, the heel bail can come free from its attachment to the crampon causing the boot to come free from the crampon.

PRODUCTS: All CAMP Tour Nanotech Automatic Crampons (ref. 367) and Tour Nanotech Semi-Automatic Crampons (ref. 374) designed for mountaineering.

REMEDY: Customers should stop use of the product immediately and contact CAMP USA Inc. for information on filing their claim.

**For More Information:
1-877-421-2267**

Monday - Friday 9am-5pm MST

www.camp-usa.com